DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004455

Address: 333 Burma Road **Date Inspected:** 06-Aug-2008

City: Oakland, CA 94607

OSM Arrival Time: 1430 **Project Name:** SAS Superstructure **OSM Departure Time:** 2230 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Jiang Jian Fei No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** Tower and OBG

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Larry Viars was present observe and monitor fabrication and perform of the Orthotropic Box Girder (OBG) and Tower components, for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

Tower Heavy Machinery Bay 1:

Caltrans QA observed ZPMC welder Mr. Cao Xiohua performing Submerged Arc welding in the 1G position on Tower Skin Plate C weld ESD1-SA296 A/E-B. Welding appeared to be in conformance with the posted welding procedure specification, WPS-B-T-2221-B-U3C-S-2.

Caltrans QA Inspector observed ZPMC in the process of fitting and tack welding Tower Skin Plate A longitudinal stiffener PJP weld ESD1-SA216 G/K-29.

Heavy Tower Machinery Bay 3:

Caltrans QA performed MT verification of ZPMC tested and accepted Deck Panel U-rib welds DP082-001 welds 2 through 6. No relevant indications were noted during verification testing. See MT report TL-6028, generated on this date for further information.

Summary of Conversations:

Only general conversations occurred between QA and QC on this date.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Joshaua Ishibashi, 137 6471 0411, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	Wright,Mark	QA Reviewer